(44)	
------	--

-	1
ÕĎ	
14 14	

•	SECRET
•	2 CULI
FINEO	(When Filled

FILEINFO	- 4	(When Fill	ed In)		
3 FE	06909902	REPRODUCTION	I PROHIBITED	3 FEB 53 10 4 9	
ACTION	1 .	6	11	16	
:	2	7	12	17	
	3	8	: 13	18	
	4	9	. 14	19	
	5	10	15	20	

SECRET 030714Z FEB 69 CITE

25X1

DIDEALIST

THIS IS AN OPS HAZARD REPORT

- 25X1 1. REQUESTS THAT A SERVICE BULLETIN BE INITIATED
- TO EQUIP THE U-2R WITH ONE (1) EXTERNAL REAR
- VIEW MIRROR AND TWO (2) INTERNAL COCKPIT MIRRORS.
 - 2. AN EXTERNAL MIRROR IS CONSIDERED ESSENTIAL TO THE
 - PILOTS. THEY USE IT AS THEIR PRIMARY MEANS OF

25X1

- DETERMINING IF THE AIRCRAFT IS CONNING, WHICH IS A MANDANTORY ABORT ITEM ON PENETRATION MISSIONS. THE
- MIRROR IS THE ONLY MEANS TO CHECK THE TAIL AREA FOR
- SUMP TANK FUEL VENTING IN CASE OF A FLOAT VALVE MAL-
 - FUNCTION. FURTHER, THE PILOTS HAVE BECOME ACCUSTOMED
- 3 TO CHECKING THE TAIL CONTROL SURFACES BEFORE TAKE-OFF
 - WITH THE EXTERNAL MIRROR.
 - 3. INTERNAL MIRRORS ARE ESSENTIAL FOR CHECK-
- ING PRESSURE SUIT FITTINGS, CONTROL VALVES, CABLES
- AND CONNECTIONS. THE NEW HELMET VISIBILITY AND PRESS-
 - URE SUIT GLOVES RESTRICT THE PILOT FROM CHECKING THESE

. .

E.S.

Approved For Release 2005/02/10 GIA-RDP75B00159R000100170036-4

SECRET

FILE INFO

(When Filled In)

* *	• • 2	·	R	EPRO	DUCTION PROHI	BITED		0.10
ACTION	. 1			6	7	11	16	7-4
	2			7	-	12	17	
. •	3			8		13	18	
er .	4	11/4		9		14	19	
3.1	5		*	100		15	2ø	

25X1PAGE 2 5521 S E C R E T

FUNCTIONS. THE POCKET MIRROR IS CONSIDERED INADE-

- QUATE, ESPECIALLY IN CASE OF A RAPID DECOMPRESSION.
- WE FEEL IT IS AN OPERATIONAL HAZARD NOT TO PROVIDE
 - THE PILOTS WITH A POSITIVE MEANS OF CHECKING HIS
 - SUIT FITTINGS. ETC.

THE RELATIVE LOW COST OF THREE MIRRORS IS CONSIDERED

A CHEAP ENOUGH PRICE TO PAY FOR THE ADDED INSURANCE AND

INCREASED NCISSION EFFECT IVENESS.

SECRET

BT